

Auditcon®

PRODUCT BULLETIN

Product:	Auditcon® 2 Series - Vertical Deadbolt
Subject:	Change in Installation Instructions
Bulletin:	A073121
Date:	September 1, 2022

- Models** **52, T52, 252, 552 Vertical Deadbolt**
- Component Change- Retainer Clip 306111
- Impact** **Change in Spindle Length Requirement for Installation**
- Change in Installation Instructions**

dormakaba is pleased to share this technical update with our valued customers and service partners. Effective immediately a revision to installation hardware component 306111 (Retainer Clip , Push on-.186, Heat Treat, RoHS). A new version of this clip will be included in all Auditcon vertical deadbolt models. This change will impact the installation instructions for these locks. The new version of this retainer clip has been released to replace an end of life component.

PLEASE BE AWARE:


When installing a lock with the new retainer clip, mark and cut the spindle to allow 1 3/8" (34.9mm) from the outside of the container door. (plus or minus 1/8" or 3.2mm)

Previous Revisions of this clip required 1 1/4" (31.8mm) from the outside of the container. This change in installation procedure is documented in the installation instructions (3045.025) .

PLEASE TAKE ACTION:

Please update any documentation for your organization and notify service personnel.

306111 Retainer Clip- Previous Rev



306111 Retainer Clip- New

