





DL/DB 1000 Series
Templates for RH or RHR Door



RH or RHR Door



RH or LHR Strike



Inside of Door

Outside of Door

INSIDE PREPARATION

FUNCTION	DRILL				
	A	B	C	D	E
1953, 1956, 1050, 1986, 1985, 1973		X	X	X	X
1070, 1080			X	X	X
1010, 1004			X	X	X
1960		X			X
1961					X
1040, 1940		X	X	X	X
1962, 1963	X				X
1060	X		X	X	X
1966, 1082	X		X	X	X


OUTSIDE PREPARATION

FUNCTION	DRILL				
	A	B	C	D	E
1953, 1956, 1050, 1986, 1985, 1973	X		X	X	X
1070, 1080	X		X	X	X
1010, 1004			X	X	X
1960	X				X
1961	X				X
1040, 1940		X	X	X	X
1962, 1963	X				X
1060	X		X	X	X
1966, 1082	X		X	X	X




DL/DB 1000 Series Templates for LH or LHR Door

LH or LHR Door



LH or RHR Strike

1" (25mm) Holes, 1 1/8" (29mm) Deep



OUTSIDE PREPARATION

FUNCTION	DRILL				
	A	B	C	D	E
1953, 1956, 1050, 1986, 1985, 1973	X		X	X	X
1070, 1080	X		X	X	X
1010, 1004			X	X	X
1960	X				X
1961	X				X
1040, 1940		X	X	X	X
1962, 1963	X				X
1060	X		X	X	X
1966, 1082	X		X	X	X

INSIDE PREPARATION

FUNCTION	DRILL				
	A	B	C	D	E
1953, 1956, 1050, 1986, 1985, 1973	X	X	X	X	X
1070, 1080			X	X	X
1010, 1004			X	X	X
1960		X			X
1961					X
1040, 1940		X	X	X	X
1962, 1963	X				X
1060	X		X	X	X
1966, 1082	X		X	X	X

Detach

Strike
Lock